



## Environmental & Agricultural Testing

"Providing Quality Analytical Services Since 1939"

2829 Reach Road, Williamsport, PA 17701 • Phone: (570) 326-4001 • Fax: (570) 326-0399 • [www.seewaldlabs.com](http://www.seewaldlabs.com)

# Certificate of Analysis

June 22, 2018

Jack Bailey

Work Order: 1814917

City of Lock Haven

Project: Beach

20 East Church St

Lock Haven, PA 17745

Dear Jack Bailey,

Enclosed is your report of analysis that contains the result(s) of the sample(s) received on 6/20/2018. Please direct any questions or comments regarding the content of this report to our Client Services Manager, Mr. Kevin Green; or the Laboratory Director, Mr. Raymond J. Martrano at (570) 326 - 4001.

Seewald Laboratories, Inc. is a National Environmental Laboratory Accreditation Program (NELAP) accredited laboratory and the analytical result(s) contained in this report meet those regulation requirements, except where noted. For example, all drinking water testing and/or analysis comply with the requirements in 40 CFR part 141. All wastewater testing and/or analysis comply with the requirements in 40 CFR part 136. All Solid and Chemical Material testing and/or analysis complies with the requirements in SW-846. All quantitative solid result(s), unless otherwise indicated, are reported on a dry weight basis obtained by a percent moisture calculation.

Sample(s) that were collected by Seewald Laboratories, Inc. personnel are done in accordance with the latest revision of the laboratory's Field Sampling and Field Analysis Standard Operating Procedures. The result(s) contained within this report are representative of the sample(s) as received. Any and all information provided to us by the client was not performed by Seewald Laboratories, Inc. and is not within our scope of accreditation. Any abnormalities in how the sample(s) were received are noted in the documentation contained herein.

All information contained within this report is the property of Seewald Laboratories, Inc. and that of the client. This report may not be reproduced in any form without prior consent from either an authorized representative of Seewald Laboratories, Inc. or the client for which this report was intended. If required, this report must be reproduced in its entirety. Seewald Laboratories, Inc. is not responsible for the use or interpretation of the data included herein.

Please visit [www.seewaldlabs.com](http://www.seewaldlabs.com) for a complete list of our accredited parameters and other topics of interest.

Regards,

Seewald Laboratories, Inc.



Approved by: \_\_\_\_\_

Ray Martrano, Laboratory Director

PA Lab ID: 41-00034 • Maryland Certificate #: 202 • Delaware Office of Drinking Water • NY State Lab ID: 12028

## Table of Contents

Certificate of Analysis/Cover Letter	1
Sample Summary	3
Analytical Results	4
Notes and Definitions	5
Work Order/COC PDF	6



**Environmental & Agricultural Testing**

*"Providing Quality Analytical Services Since 1939"*

2829 Reach Road, Williamsport, PA 17701 • Phone: (570) 326-4001 • Fax: (570) 326-0399 • [www.seewaldlabs.com](http://www.seewaldlabs.com)

City of Lock Haven

**Project:** Beach

20 East Church St

**Project Number:**

Lock Haven, PA 17745

**Reported:** 06/22/2018 11:37

## Sample Summary

Lab ID	Sample	Matrix	Sampled	Received
1814917-01	City Beach	Non-Potable Water	06/20/2018 09:00	06/20/2018 14:15





**Environmental & Agricultural Testing**

"Providing Quality Analytical Services Since 1939"

2829 Reach Road, Williamsport, PA 17701 • Phone: (570) 326-4001 • Fax: (570) 326-0399 • [www.seewaldlabs.com](http://www.seewaldlabs.com)

City of Lock Haven	<b>Project:</b> Beach
20 East Church St	<b>Project Number:</b>
Lock Haven, PA 17745	<b>Reported:</b> 06/22/2018 11:37

## Analytical Results

<b>Sample ID:</b> City Beach	<b>Sampled:</b> 06/20/2018 09:00
<b>Lab ID:</b> 1814917-01	<b>Received:</b> 06/20/2018 14:15
<b>Matrix:</b> Non-Potable Water	

Analyte	Result	Units	Qualifier	Reporting Limit	Prepared	Analyzed	Method	Analyst
---------	--------	-------	-----------	-----------------	----------	----------	--------	---------

**Microbiology**

E. coli (enumeration)	52	MPN/100 mL		1	6/20/18 15:20	6/21/18 11:50	SM 9223 B/Quanti-Tray	BF
-----------------------	----	------------	--	---	---------------	---------------	-----------------------	----





## Environmental & Agricultural Testing

"Providing Quality Analytical Services Since 1939"

2829 Reach Road, Williamsport, PA 17701 • Phone: (570) 326-4001 • Fax: (570) 326-0399 • [www.seewaldlabs.com](http://www.seewaldlabs.com)

City of Lock Haven

**Project:** Beach

20 East Church St

**Project Number:**

Lock Haven, PA 17745

**Reported:** 06/22/2018 11:37

## Notes and Definitions

Item	Definition
ND	Not Detected at or above the Minimum Reporting Limit
Reporting Limit	This value represents the minimum concentration that the target analyte can be identified and quantitated with confidence
(2)	Indicates the data was reported from the instrument's secondary column. When applicable the (2) will follow the analyte's name on the results page.



